

Contract No. DC/2022/02
Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C1A

Location	Date	Weather	Time	Water Depth (m)	Dissolved Oxygen (mg/L)		Dissolved Oxygen Saturation (%)		pH		Salinity (ppt)		Tempertuare (°C)		Turbidity (NTU)		Suspended Solids (mg/L)		Remark
					Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	
C1A	20250303	Fine	11:09	0.38	6.74	6.74	76.5	76.7	7.84	7.84	0.18	0.18	24.5	24.5	4.03	4.03	2.3	2.0	
C1A	20250303	Fine	11:09	0.38	6.74		76.9		7.84		0.18		24.5		4.03		1.7		
C1A	20250310	Sunny	12:47	0.4	6.84	6.84	69.6	69.6	7.2	7.20	0.34	0.34	22.3	22.3	9.59	9.58	3.5	3.2	
C1A	20250310	Sunny	12:47	0.4	6.84		69.6		7.2		0.34		22.3		9.56		2.9		
C1A	20250317	Cloudy	10:57	0.4	6.78	6.78	69.0	69.1	7.39	7.39	0.39	0.39	18.3	18.3	9.76	9.76	2.0	2.6	
C1A	20250317	Cloudy	10:57	0.4	6.78		69.2		7.39		0.39		18.3		9.75		3.1		
C1A	20250324	Sunny	12:46	0.4	6.73	6.73	68.3	68.3	7.29	7.29	0.40	0.40	22.5	22.5	7.32	7.32	4.8	4.4	
C1A	20250324	Sunny	12:46	0.4	6.73		68.3		7.29		0.40		22.5		7.32		4.0		
C1A	20250331	Rainy	12:37	0.38	6.77	6.77	77.1	77.1	7.26	7.26	0.26	0.26	15.9	15.9	10.10	10.15	2.2	2.4	
C1A	20250331	Rainy	12:37	0.38	6.77		77.1		7.26		0.26		15.9		10.20		2.5		

Contract No. DC/2022/02
Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C2

Location	Date	Weather	Time	Water Depth (m)	Dissolved Oxygen (mg/L)		Dissolved Oxygen Saturation (%)		pH		Salinity (ppt)		Tempertuare (°C)		Turbidity (NTU)		Suspended Solids (mg/L)		Remark
					Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	
C2	20250303	Fine	10:58	0.4	5.60	5.6	59.1	59.1	7.32	7.32	0.23	0.23	22.2	22.2	9.34	9.48	9.2	7.8	
C2	20250303	Fine	10:58	0.4	5.60		59.0		7.32		0.23		22.2		9.62		6.3		
C2	20250310	Sunny	12:39	0.42	6.13	6.13	61.2	61.2	7.21	7.21	0.20	0.20	22.7	22.7	9.97	9.98	8.4	7.6	
C2	20250310	Sunny	12:39	0.42	6.13		61.2		7.21		0.20		22.7		9.99		6.7		
C2	20250317	Cloudy	10:47	0.41	5.18	5.18	53.8	53.8	7.24	7.24	0.18	0.18	17.7	17.7	9.85	9.87	4.9	3.9	
C2	20250317	Cloudy	10:47	0.41	5.18		53.8		7.24		0.18		17.7		9.89		2.9		
C2	20250324	Sunny	12:35	0.42	4.53	4.53	45.8	45.8	7.33	7.33	0.22	0.22	21.8	21.8	13.80	13.75	7.7	7.3	
C2	20250324	Sunny	12:35	0.42	4.53		45.8		7.33		0.22		21.8		13.69		6.9		
C2	20250331	Rainy	12:28	0.4	5.76	5.78	57.5	57.7	7.2	7.20	0.17	0.17	15.3	15.3	24.56	24.56	7.3	10.7	
C2	20250331	Rainy	12:28	0.4	5.80		57.9		7.19		0.17		15.3		24.55		14.0		

Contract No. DC/2022/02
 Drainage Improvement Works at Yuen Long -
 Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
 Water Quality Monitoring Result



Water Quality Monitoring Location: C3A

Location	Date	Weather	Time	Water Depth (m)	Dissolved Oxygen (mg/L)		Dissolved Oxygen Saturation (%)		pH		Salinity (ppt)		Temperature (°C)		Turbidity (NTU)		Suspended Solids (mg/L)		Remark
					Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	
C3A	20250303	Fine	10:53	0.5	7.27	7.3	80.0	80.4	7.41	7.37	0.02	0.02	20	20.0	5.02	5.1	2.7	2.9	
C3A	20250303	Fine	10:53	0.5	7.33		80.7		7.33		0.02		20		5.17		3.1		
C3A	20250310	Sunny	12:33	0.5	7.96	7.96	86.3	86.3	7.54	7.53	0.02	0.02	19.3	19.3	5.01	5.02	2.0	2.0	
C3A	20250310	Sunny	12:33	0.5	7.95		86.2		7.52		0.02		19.2		5.02		2.0		
C3A	20250317	Cloudy	10:45	0.5	8.38	8.38	85.8	85.8	6.76	6.75	0.02	0.02	17	17.0	7.07	7.11	3.9	3.5	
C3A	20250317	Cloudy	10:45	0.5	8.38		85.8		6.73		0.02		17		7.15		3.0		
C3A	20250324	Sunny	12:25	0.5	8.72	8.72	89.8	89.8	7.43	7.43	0.02	0.02	18.6	18.6	14.66	14.68	6.5	6.4	
C3A	20250324	Sunny	12:25	0.5	8.72		89.8		7.43		0.02		18.6		14.70		6.3		
C3A	20250331	Rainy	12:20	0.5	8.20	8.20	80.7	80.7	7.91	7.91	0.02	0.02	14.7	14.7	6.04	6.04	4.7	4.3	
C3A	20250331	Rainy	12:20	0.5	8.20		80.7		7.91		0.02		14.7		6.04		3.8		

Contract No. DC/2022/02
Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C4

Location	Date	Weather	Time	Water Depth (m)	Dissolved Oxygen (mg/L)		Dissolved Oxygen Saturation (%)		pH		Salinity (ppt)		Tempertuare (°C)		Turbidity (NTU)		Suspended Solids (mg/L)		Remark
					Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	
C4	20250303	Fine	12:48	0.1	8.01	8.01	96.2	96.2	7.17	7.18	0.05	0.05	25.2	25.2	58.90	59.09	27.0	34.2	
C4	20250303	Fine	12:48	0.1	8.00		96.1		7.18		0.05		25.2		59.27		41.4		
C4	20250305	Cloudy	10:26	0.08	8.65	8.65	86.8	86.8	7.33	7.35	0.06	0.06	19.9	19.9	28.95	29.91	12.0	12.0	
C4	20250305	Cloudy	10:26	0.08	8.65		86.7		7.36		0.06		19.9		29.91		12.0		
C4	20250307	Cloudy	10:34	0.06	8.43	8.42	82.0	81.9	7.5	7.5	0.05	0.05	14.1	14.1	32.36	32.47	28.0	35.0	
C4	20250307	Cloudy	10:34	0.06	8.41		81.8		7.49		0.05		14.1		32.58		42.0		
C4	20250310	Cloudy	11:23	0.1	7.54	7.54	83.0	83.0	7.14	7.14	0.05	0.05	20	20.0	120.39	119.88	151.0	122.0	
C4	20250310	Cloudy	11:23	0.1	7.54		83.0		7.13		0.05		20		119.37		93.0		
C4	20250312	Fine	10:33	0.06	8.18	8.18	85.0	85.1	7.28	7.29	0.06	0.06	21	21.0	59.09	59.56	47.0	62.5	
C4	20250312	Fine	10:33	0.06	8.18		85.1		7.30		0.06		21		60.03		78.0		
C4	20250314	Fine	10:36	0.06	8.78	8.78	93.1	93.1	6.95	6.95	0.05	0.05	23.6	23.6	54.27	54.29	48.0	57.0	
C4	20250314	Fine	10:36	0.06	8.78		93.1		6.95		0.05		23.6		54.30		66.0		
C4	20250317	Cloudy	12:23	0.12	8.75	8.75	91.6	91.6	7.00	7.00	0.05	0.05	17.5	17.5	42.63	42.65	19.0	27.0	
C4	20250317	Cloudy	12:23	0.12	8.75		91.6		6.99		0.05		17.5		42.67		35.0		
C4	20250319	Sunny	10:22	0.08	8.79	8.79	90.6	90.7	7.02	7.02	0.05	0.05	16.8	16.8	77.21	77.2	39.0	35.5	
C4	20250319	Sunny	10:22	0.08	8.79		90.7		7.02		0.05		16.8		77.18		32.0		
C4	20250321	Sunny	10:25	0.14	8.49	8.49	88.9	89.0	6.78	6.78	0.05	0.05	17.6	17.6	64.15	64.87	72.0	67.5	
C4	20250321	Sunny	10:25	0.14	8.49		89.0		6.78		0.05		17.6		65.58		63.0		
C4	20250324	Sunny	11:43	0.16	8.76	8.76	86.1	86.1	7.35	7.35	0.05	0.05	21.0	21.0	71.18	71.68	50.0	56.0	
C4	20250324	Sunny	11:43	0.16	8.76		86.1		7.34		0.05		21.0		72.18		62.0		
C4	20250326	Sunny	10:32	0.17	8.49	8.49	88.9	89.0	7.51	7.51	0.05	0.05	21.5	21.5	52.72	52.59	36.0	39.5	
C4	20250326	Sunny	10:32	0.17	8.49		89.0		7.51		0.05		21.5		52.45		43.0		
C4	20250328	Cloudy	10:28	0.12	5.45	5.45	62.6	62.6	7.51	7.52	0.04	0.04	22.2	22.2	10.99	10.99	6.2	7.9	
C4	20250328	Cloudy	10:28	0.12	5.45		62.6		7.52		0.04		22.2		10.99		9.5		
C4	20250329	Cloudy	12:47	0.13	5.71	5.71	60.8	60.9	NA	NA	NA	NA	NA	NA	NA	NA	NA	Additional DO Monitoring for DO Action Level Exceedance at C5 on 28 Mar 2025	
C4	20250329	Cloudy	12:47	0.13	5.71		60.9		NA		NA		NA		NA		NA		
C4	20250331	Rainy	11:35	0.16	8.77	8.76	84.8	84.7	7.62	7.61	0.08	0.08	13.8	13.8	5.72	5.7	5.9		
C4	20250331	Rainy	11:35	0.16	8.74		84.5		7.59		0.08		13.8		5.68		3.3		4.6

Contract No. DC/2022/02
Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C5

Location	Date	Weather	Time	Water Depth (m)	Dissolved Oxygen (mg/L)		Dissolved Oxygen Saturation (%)		pH		Salinity (ppt)		Tempertuare (°C)		Turbidity (NTU)		Suspended Solids (mg/L)		Remark
					Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	
C5	20250303	Fine	12:53	0.05	8.41	8.41	87.0	87.0	7.72	7.72	0.08	0.08	24.6	24.6	2.93	2.93	1.6	1.3	
C5	20250303	Fine	12:53	0.05	8.41		87.0		7.72		0.08		24.6		2.93		1.0		
C5	20250305	Cloudy	11:25	0.06	8.56	8.56	85.5	85.5	7.62	7.61	0.08	0.08	20.1	20.1	5.33	5.32	7.7	5.9	
C5	20250305	Cloudy	11:25	0.06	8.56		85.5		7.59		0.08		20.1		5.31		4.1		
C5	20250307	Cloudy	10:35	0.04	8.62	8.65	84.1	84.4	7.26	7.27	0.09	0.09	14.3	14.3	7.36	7.32	<1.0	<1.0	
C5	20250307	Cloudy	10:35	0.04	8.67		84.6		7.27		0.09		14.3		7.27		<1.0		
C5	20250310	Cloudy	11:25	0.06	8.41	8.41	81.6	81.6	7.78	7.76	0.08	0.08	19.1	19.2	4.46	4.42	<1.0	<1.0	
C5	20250310	Cloudy	11:25	0.06	8.41		81.6		7.74		0.08		19.2		4.38		<1.0		
C5	20250312	Fine	10:34	0.02	8.45	8.45	89.3	89.3	7.23	7.38	0.08	0.08	19.9	19.9	5.29	5.3	<1.0	<1.0	
C5	20250312	Fine	10:34	0.02	8.45		89.3		7.53		0.08		19.9		5.31		<1.0		
C5	20250314	Fine	10:34	0.04	8.38	8.38	85.6	85.6	7.17	7.17	0.08	0.08	22.4	22.4	5.75	5.74	<1.0	<1.0	
C5	20250314	Fine	10:34	0.04	8.38		85.6		7.16		0.08		22.4		5.73		<1.0		
C5	20250317	Cloudy	12:25	0.08	8.41	8.42	87.0	87.1	7.22	7.23	0.09	0.09	17.0	17.0	5.82	5.82	<1.0	<1.0	
C5	20250317	Cloudy	12:25	0.08	8.42		87.1		7.24		0.09		17.0		5.81		<1.0		
C5	20250319	Cloudy	10:24	0.02	8.46	8.48	87.1	87.3	7.14	7.15	0.08	0.08	16.8	16.8	4.68	4.71	<1.0	<1.0	
C5	20250319	Cloudy	10:24	0.02	8.49		87.5		7.16		0.08		16.8		4.74		<1.0		
C5	20250321	Sunny	10:30	0.04	8.37	8.37	85.2	85.3	7.08	7.08	0.08	0.08	16.4	16.4	4.87	4.88	6.5	6.1	
C5	20250321	Sunny	10:30	0.04	8.37		85.3		7.08		0.08		16.4		4.89		5.6		
C5	20250324	Sunny	11:50	0.05	8.45	8.45	89.5	89.5	7.34	7.34	0.09	0.09	18.2	18.2	4.30	4.33	<1.0	1.1	
C5	20250324	Sunny	11:50	0.05	8.45		89.5		7.33		0.09		18.2		4.36		1.2		
C5	20250326	Sunny	10:30	0.04	8.36	8.36	84.8	84.8	7.66	7.66	0.09	0.09	20.5	20.5	3.98	3.98	<1.0	1.1	
C5	20250326	Sunny	10:30	0.04	8.36		84.8		7.66		0.09		20.5		3.98		1.1		
C5	20250328	Cloudy	10:38	0.07	5.78	5.78	66.5	66.5	7.31	7.31	0.08	0.08	22.3	22.3	4.95	4.95	<1.0	<1.0	
C5	20250328	Cloudy	10:38	0.07	5.78		66.5		7.31		0.08		22.3		4.95		<1.0		
C5	20250329	Cloudy	12:52	0.07	6.14	6.14	64.6	64.6	NA	NA	NA	NA	NA	NA	NA	NA	NA	Additional DO Monitoring for DO Action Level Exceedance at C5 on 28 Mar 2025	
C5	20250329	Cloudy	12:52	0.07	6.14		64.6		NA		NA		NA		NA		NA		
C5	20250331	Rainy	11:43	0.05	8.9	8.9	85.7	85.7	7.36	7.36	0.08	0.08	13.6	13.6	5.61	5.62	<1.0		
C5	20250331	Rainy	11:43	0.05	8.9		85.7		7.35		0.08		13.6		5.63		<1.0		<1.0

Contract No. DC/2022/02
Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C6

Location	Date	Weather	Time	Water Depth (m)	Dissolved Oxygen (mg/L)		Dissolved Oxygen Saturation (%)		pH		Salinity (ppt)		Tempertuare (°C)		Turbidity (NTU)		Suspended Solids (mg/L)		Remark
					Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	
C6	20250303	Fine	10:53	0.24	5.73	5.73	59.0	59.0	8.03	8.03	1.34	1.34	19.6	19.6	28.90	28.91	12.0	12.0	
C6	20250303	Fine	10:53	0.24	5.73		59.0		8.03		1.34		19.6		28.92		12.0		
C6	20250310	Sunny	11:23	0.22	7.50	7.5	74.7	74.7	7.2	7.21	0.09	0.09	15.2	15.2	4.62	4.59	23.0	20.0	
C6	20250310	Sunny	11:23	0.22	7.50		74.7		7.21		0.09		15.2		4.56		17.0		
C6	20250317	Cloudy	11:45	0.24	6.32	6.32	67.6	67.6	7.36	7.36	0.16	0.16	18.5	18.5	7.36	7.36	7.8	6.2	
C6	20250317	Cloudy	11:45	0.24	6.32		67.6		7.36		0.16		18.5		7.36		4.5		
C6	20250324	Sunny	10:52	0.22	6.47	6.47	66.2	66.2	7.92	7.92	0.91	0.91	20.8	20.8	30.26	30.07	37.0	30.0	
C6	20250324	Sunny	10:52	0.22	6.47		66.2		7.92		0.91		20.7		29.88		23.0		
C6	20250331	Rainy	10:47	0.24	8.67	8.66	83.6	83.4	7.66	7.66	0.18	0.18	13.6	13.6	7.83	7.81	24.0	18.5	
C6	20250331	Rainy	10:47	0.24	8.64		83.2		7.65		0.18		13.6		7.79		13.0		

Contract No. DC/2022/02
Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C7A

Location	Date	Weather	Time	Water Depth (m)	Dissolved Oxygen (mg/L)		Dissolved Oxygen Saturation (%)		pH		Salinity (ppt)		Tempertuare (°C)		Turbidity (NTU)		Suspended Solids (mg/L)		Remark
					Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	
C7A	20250303	Fine	12:30	0.1	5.89	5.89	60.3	60.3	7.25	7.25	0.16	0.16	23.9	23.9	6.90	6.91	8.2	8.5	
C7A	20250303	Fine	12:30	0.1	5.89		60.3		7.25		0.16		23.9		6.92		8.7		
C7A	20250310	Sunny	11:03	0.1	8.52	8.52	88.6	88.6	7.4	7.40	0.17	0.17	20	20.0	68.15	68.37	18.0	14.5	
C7A	20250310	Sunny	11:03	0.1	8.52		88.6		7.4		0.17		20		68.59		11.0		
C7A	20250317	Cloudy	11:53	0.1	5.98	5.99	63.0	63.2	7.78	7.78	0.60	0.60	17.7	17.7	16.83	16.83	4.2	4.4	
C7A	20250317	Cloudy	11:53	0.1	6.00		63.3		7.78		0.60		17.7		16.83		4.5		
C7A	20250324	Sunny	11:05	0.1	6.20	6.2	64.3	64.3	7.56	7.56	0.18	0.18	21.8	21.8	7.16	7.16	6.2	5.8	
C7A	20250324	Sunny	11:05	0.1	6.20		64.3		7.56		0.18		21.8		7.15		5.4		
C7A	20250331	Rainy	11:08	0.1	5.74	5.76	57.5	57.7	7.44	7.44	0.18	0.18	15.4	15.4	8.13	8.14	6.0	5.7	
C7A	20250331	Rainy	11:08	0.1	5.78		57.9		7.44		0.18		15.4		8.15		5.3		

Contract No. DC/2022/02
Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C8

Location	Date	Weather	Time	Water Depth (m)	Dissolved Oxygen (mg/L)		Dissolved Oxygen Saturation (%)		pH		Salinity (ppt)		Tempertuare (°C)		Turbidity (NTU)		Suspended Solids (mg/L)		Remark
					Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	
C8	20250303	Fine	12:36	0.05	6.13	6.13	61.2	61.1	7.67	7.68	0.10	0.10	25.0	25.0	2.14	2.15	<1.0	1.1	
C8	20250303	Fine	12:36	0.05	6.13		61.0		7.68		0.10		25.0		2.16		1.2		
C8	20250310	Sunny	11:13	0.05	6.22	6.21	62.2	62.0	7.68	7.68	0.24	0.24	21.1	21.1	6.49	6.43	2.1	2.3	
C8	20250310	Sunny	11:13	0.05	6.20		61.8		7.68		0.24		21.1		6.36		2.5		
C8	20250317	Cloudy	11:13	0.11	5.55	5.55	58.0	58.1	7.29	7.29	0.17	0.17	19.0	19.0	6.51	6.52	1.8	1.7	
C8	20250317	Cloudy	11:13	0.11	5.55		58.1		7.29		0.17		19.0		6.53		1.6		
C8	20250324	Sunny	11:31	0.05	5.67	5.67	64.7	64.7	7.5	7.49	0.20	0.20	21.6	21.6	7.17	7.25	1.5	1.7	
C8	20250324	Sunny	11:31	0.05	5.67		64.7		7.48		0.20		21.6		7.32		1.9		
C8	20250331	Rainy	11:15	0.05	5.47	5.47	62.5	62.5	7.47	7.44	0.13	0.13	16.6	16.6	4.43	4.54	<1.0	1.2	
C8	20250331	Rainy	11:15	0.05	5.46		62.5		7.41		0.13		16.6		4.65		1.3		

Contract No. DC/2022/02
Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C9

Location	Date	Weather	Time	Water Depth (m)	Dissolved Oxygen (mg/L)		Dissolved Oxygen Saturation (%)		pH		Salinity (ppt)		Tempertuare (°C)		Turbidity (NTU)		Suspended Solids (mg/L)		Remark
					Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	
C9	20250303	Fine	11:34	0.19	8.06	8.06	89.0	89.1	7.62	7.63	0.07	0.07	20.2	20.2	9.51	9.34	20.0	17.0	
C9	20250303	Fine	11:34	0.19	8.06		89.1		7.63		0.07		20.2		9.16		14.0		
C9	20250310	Sunny	10:14	0.18	8.62	8.63	90.1	90.2	7.65	7.65	0.07	0.07	17.4	17.4	3.90	3.75	5.4	6.2	
C9	20250310	Sunny	10:14	0.18	8.63		90.2		7.65		0.07		17.4		3.60		7.0		
C9	20250317	Cloudy	10:04	0.18	8.42	8.42	88.8	88.8	6.98	6.98	0.06	0.06	17.9	17.9	3.62	3.56	12.0	16.5	
C9	20250317	Cloudy	10:04	0.18	8.42		88.8		6.98		0.06		17.9		3.50		21.0		
C9	20250324	Sunny	10:18	0.18	8.62	8.62	90.4	90.4	7.57	7.57	0.08	0.08	17.6	17.6	2.62	2.63	12.0	11.5	
C9	20250324	Sunny	10:18	0.18	8.62		90.4		7.57		0.08		17.6		2.63		11.0		
C9	20250331	Rainy	10:20	0.19	9.49	9.49	94.6	94.6	8.14	8.13	0.07	0.07	15.2	15.2	5.83	5.73	5.5	6.5	
C9	20250331	Rainy	10:20	0.19	9.48		94.5		8.12		0.07		15.2		5.63		7.5		


Contract No. DC/2022/02
Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result







Water Quality Monitoring Location: C10

Location	Date	Weather	Time	Water Depth (m)	Dissolved Oxygen (mg/L)		Dissolved Oxygen Saturation (%)		pH		Salinity (ppt)		Tempertuare (°C)		Turbidity (NTU)		Suspended Solids (mg/L)		Remark
					Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	
C10	20250303	Fine	11:42	0.18	3.60	3.61	41.8	41.9	7.15	7.16	0.14	0.14	22.8	22.8	10.13	10.09	3.3	4.5	
C10	20250303	Fine	11:42	0.18	3.61		42.0		7.16		0.14		22.8		10.05		5.6		
C10	20250310	Sunny	10:22	0.16	2.67	2.66	28.9	28.8	7.02	7.02	0.13	0.13	19.1	19.1	17.51	17.72	3.5	3.7	
C10	20250310	Sunny	10:22	0.16	2.65		28.7		7.02		0.13		19.1		17.93		3.8		
C10	20250317	Cloudy	10:16	0.18	4.19	4.22	45.1	45.4	6.84	6.84	0.13	0.13	18.8	18.8	13.21	12.96	3.9	3.4	
C10	20250317	Cloudy	10:16	0.18	4.24		45.6		6.83		0.13		18.8		12.71		2.9		
C10	20250324	Sunny	10:28	0.16	3.57	3.56	39.1	39.0	7.17	7.17	0.15	0.15	19.8	19.8	13.45	13.45	13.0	11.2	
C10	20250324	Sunny	10:28	0.16	3.54		38.8		7.16		0.15		19.8		13.45		9.3		
C9	20250331	Rainy	10:08	0.18	4.94	4.94	50.0	49.9	7.46	7.46	0.16	0.16	15.8	15.8	11.21	11.21	5.0	4.8	
C9	20250331	Rainy	10:08	0.18	4.93		49.8		7.45		0.16		15.8		11.21		4.6		


Monitoring Location: C10




Monitoring Location: C9




Monitoring Location: C8



Monitoring Location: C7A




Monitoring Location: C6







Monitoring Location: C5







Monitoring Location: C4



Monitoring Location: C3A



Monitoring Location: C2





Monitoring Location: C1A

