

Figure 2.1 Impact Water Quality Monitoring Locations




	Legend:					
	Legenu.					
		Work Lir	nit Boun	dary		
		500 m st	tudy area	а		
	•	Control S	Station			
		Alternati	ve Conti	rol Sta	atior	n
		Alternati				
	-	Flow dire	ection			
SUSER 6						
	Project Title:					
	COI					3
	DRAINAGE IMPROVEMENT WORKS AT YUEN LONG - STAGE 2					
	Figure Title:	01/1				
	Water Q	uality Mon			ıs at	
		Sung Shan		.9e		
	Drawn by:		Scale:	1:5,00	0 с	on A3
	Checked By:		Date:			
	Approved by:					
	Figure Number:	Figur	e 2.1a		Revi	sion:

	Revision:
I	R1



DO NOT SCALE	
/ / 大窩	
/ / TAI WO	Pat HUNG KIN ROAD LIN FA TEL
	PA BOND
OW IAT	
	TAL
	KEY PLAN
30	N.TS.
客業花園 Kai Yip Garden	
3P 3C	
/7	
311	
	Control Station
FP L _u 20.6	
Ен	Impact Station
	Flow Direction
20.7	
20.8 A	
16.0	
	A OCT 2022 TENDER ADDENDUM NO.3 SHC WCTT #
	- JUL 2022 ISSUE FOR TENDER SHC WCTT KP Rev. Date Description By Chkd App'd
	Drawing Status Suitability
	ATKINS
	Member of the SNC-Lavalin Group
	集務署 Drainage Services Department
I C T	工程管理部 Project Management Division
	CONTRACT NO. DC/2022/02
YTT X	DRAINAGE IMPROVEMENT WORKS AT YUEN LONG -
	STAGE 2
	Water Quality Monitoring Locations
$ \rangle$	at Tai Wo
	Scale Designed Drawn Checked Authorised 1:500 SHC AC WCTT KP
22.9 Å	Original Size Date Date Date Date Date A1 JUL 2022 JUL 2022 JUL 2022 JUL 2022 JUL 2022
0 5 10 15 20 25 m	Drawing Number Figure 2.1b

Copyright (C) Atkins Limited (2014)



Copyright (C) Atkins Limited (2014)

