

Appendix 2.4 Impact Water Quality Monitoring Data

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C1A

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C1A	20240604	Cloudy	16:09	6.86	81.7	7.49	0.10	24.20	7.26	<2.5	/
C1A	20240604	Cloudy	16:09	6.83	81.4	7.47	0.10	24.20	6.97	<2.5	/
C1A	20240606	Cloudy	15:34	6.93	83.4	7.28	0.06	25.20	4.05	<2.5	/
C1A	20240606	Cloudy	15:34	6.91	83.1	7.26	0.06	25.20	3.99	<2.5	/
C1A	20240608	Cloudy	11:54	6.98	85.0	7.11	0.07	25.50	3.61	<2.5	/
C1A	20240608	Cloudy	11:55	7.09	86.3	7.14	0.07	25.50	3.49	<2.5	/
C1A	20240611	Cloudy	15:41	7.05	90.5	7.37	0.06	28.20	4.36	<2.5	/
C1A	20240611	Cloudy	15:41	7.05	90.3	7.35	0.06	28.20	4.31	<2.5	/
C1A	20240613	Cloudy	15:35	6.80	88.6	7.47	0.06	29.80	4.21	<2.5	/
C1A	20240613	Cloudy	15:36	6.78	88.2	7.43	0.06	29.80	4.01	<2.5	/
C1A	20240615	Cloudy	11:00	6.80	84.6	7.55	0.06	28.10	5.38	<2.5	/
C1A	20240615	Cloudy	11:00	6.88	85.8	7.53	0.06	28.10	5.24	<2.5	/
C1A	20240618	Sunny	14:38	6.80	89.7	7.56	0.05	28.10	4.48	<2.5	/
C1A	20240618	Sunny	14:38	6.77	89.3	7.53	0.05	28.10	4.5	<2.5	/
C1A	20240620	Sunny	15:45	7.60	101.4	7.60	0.05	30.50	5.19	<2.5	/
C1A	20240620	Sunny	15:45	7.60	101.4	7.49	0.05	30.50	5.23	<2.5	/
C1A	20240622	Sunny	11:30	6.80	84.8	7.77	0.05	28.50	5.16	<2.5	/
C1A	20240622	Sunny	11:30	6.78	84.5	7.78	0.05	28.50	5.18	<2.5	/
C1A	20240625	Sunny	15:33	7.41	98.7	7.52	0.06	30.40	5.28	<2.5	/
C1A	20240625	Sunny	15:33	7.41	98.6	7.51	0.06	30.40	5.25	<2.5	/
C1A	20240627	Sunny	15:31	6.93	91.6	7.56	0.06	31.70	5.23	<2.5	/
C1A	20240627	Sunny	15:31	6.93	91.6	7.55	0.06	31.70	5.25	<2.5	/
C1A	20240629	Sunny	11:38	6.90	86.0	7.85	0.08	27.50	6.56	<2.5	/
C1A	20240629	Sunny	11:38	6.88	85.8	7.88	0.08	27.50	6.26	<2.5	/

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C2

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C2	20240604	Cloudy	15:57	6.89	82.0	7.43	0.09	24.10	6.48	5	/
C2	20240604	Cloudy	15:58	6.87	81.8	7.42	0.09	24.10	6.47	5	/
C2	20240606	Cloudy	15:25	5.79	70.5	7.27	0.06	25.30	4.51	3	/
C2	20240606	Cloudy	15:25	5.70	69.4	7.23	0.06	25.30	4.37	4	/
C2	20240608	Cloudy	11:41	5.88	71.6	7.07	0.05	25.40	4.31	<2.5	/
C2	20240608	Cloudy	11:41	5.80	70.6	7.03	0.05	25.40	4.21	<2.5	/
C2	20240611	Cloudy	15:32	6.61	84.5	7.26	0.06	28.10	4.21	3	/
C2	20240611	Cloudy	15:32	6.60	84.5	7.25	0.06	28.10	4.28	3	/
C2	20240613	Cloudy	15:28	6.18	81.4	7.39	0.06	29.80	3.97	<2.5	/
C2	20240613	Cloudy	15:28	6.17	81.4	7.38	0.06	29.80	4	3	/
C2	20240615	Cloudy	10:48	8.13	101.4	7.74	0.06	26.60	4.37	<2.5	/
C2	20240615	Cloudy	10:48	8.14	101.4	7.73	0.06	26.60	4.32	<2.5	/
C2	20240618	Sunny	14:27	6.29	82.9	7.44	0.06	26.50	5.58	<2.5	/
C2	20240618	Sunny	14:27	6.27	82.7	7.45	0.06	26.50	5.43	3	/
C2	20240620	Sunny	15:37	7.58	100.7	7.49	0.05	30.30	6.2	5	/
C2	20240620	Sunny	15:37	7.57	100.6	7.48	0.05	30.30	6.24	5	/
C2	20240622	Sunny	11:18	7.23	90.1	7.43	0.08	28.10	5.55	3	/
C2	20240622	Sunny	11:19	7.25	90.4	7.43	0.08	28.10	5.63	4	/
C2	20240625	Sunny	15:25	7.32	97.4	7.47	0.06	30.30	6.4	3	/
C2	20240625	Sunny	15:25	7.32	97.4	7.47	0.06	30.30	6.31	4	/
C2	20240627	Sunny	15:18	6.65	90.5	7.72	0.06	31.70	5.01	3	/
C2	20240627	Sunny	15:18	6.64	90.4	7.71	0.06	31.60	5.07	3	/
C2	20240629	Sunny	11:27	6.55	81.7	7.63	0.10	28.20	5.83	4	/
C2	20240629	Sunny	11:27	6.57	81.9	7.64	0.10	28.20	5.79	5	/

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -

Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che

Water Quality Monitoring Result



Water Quality Monitoring Location: C3A

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C3A	20240604	Cloudy	15:43	8.23	97.2	7.24	0.02	23.70	7.63	4	/
C3A	20240604	Cloudy	15:43	8.23	97.2	7.20	0.02	23.70	7.54	6	/
C3A	20240606	Cloudy	15:09	8.07	96.7	7.61	0.02	24.40	7.89	4	/
C3A	20240606	Cloudy	15:09	8.07	96.7	7.58	0.02	24.40	7.31	5	/
C3A	20240608	Cloudy	11:26	7.63	92.9	7.51	0.02	24.80	6.65	<2.5	/
C3A	20240608	Cloudy	11:26	7.81	95.1	7.50	0.02	24.80	6.31	<2.5	/
C3A	20240611	Cloudy	15:17	7.92	100	7.43	0.02	27.40	8.47	6	/
C3A	20240611	Cloudy	15:18	7.92	100	7.41	0.02	27.40	8.44	5	/
C3A	20240613	Cloudy	15:14	7.77	99.4	7.17	0.02	28.10	7.1	3	/
C3A	20240613	Cloudy	15:14	7.77	99.4	7.17	0.02	28.10	6.99	4	/
C3A	20240615	Cloudy	10:38	7.77	96.9	7.19	0.05	27.30	6.13	3	/
C3A	20240615	Cloudy	10:38	7.77	96.9	7.19	0.05	27.30	6.19	5	/
C3A	20240618	Sunny	14:15	7.58	100	7.20	0.04	27.40	6.66	<2.5	/
C3A	20240618	Sunny	14:15	7.54	99.4	7.20	0.04	27.40	6.73	<2.5	/
C3A	20240620	Sunny	15:20	7.97	102.7	7.64	0.02	28.50	6.84	4	/
C3A	20240620	Sunny	15:20	7.96	102.6	7.63	0.02	28.50	6.85	5	/
C3A	20240622	Sunny	11:05	7.81	97.4	7.50	0.03	27.50	4.21	<2.5	/
C3A	20240622	Sunny	11:05	7.85	97.9	7.50	0.03	27.50	4.18	<2.5	/
C3A	20240625	Sunny	15:18	7.37	98	7.60	0.06	30.30	3.55	4	/
C3A	20240625	Sunny	15:18	7.35	97.7	7.58	0.06	30.30	3.66	7	/
C3A	20240627	Sunny	14:58	7.96	103.6	7.91	0.02	29.10	6.3	3	/
C3A	20240627	Sunny	14:58	7.96	103.7	7.89	0.02	29.10	6.48	4	/
C3A	20240629	Sunny	11:12	6.71	83.7	7.60	0.06	27.90	6.49	3	/
C3A	20240629	Sunny	11:12	6.75	84.2	7.60	0.06	27.90	6.57	2	/

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C6

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C6	20240604	Cloudy	14:21	8.96	104.9	7.88	0.07	23.20	8.84	9	/
C6	20240604	Cloudy	14:21	8.96	104.8	7.87	0.07	23.20	9.19	9	/
C6	20240606	Cloudy	14:04	8.81	105.3	8.18	0.06	24.30	5.00	6	/
C6	20240606	Cloudy	14:04	8.82	105.4	8.15	0.06	24.30	5.10	6	/
C6	20240608	Cloudy	10:07	7.33	89.2	8.01	0.07	24.50	4.80	<2.5	/
C6	20240608	Cloudy	10:07	7.42	90.3	7.99	0.07	24.50	4.71	<2.5	/
C6	20240611	Cloudy	14:11	8.47	104	7.67	0.06	25.80	4.32	3	/
C6	20240611	Cloudy	14:11	8.47	104	7.66	0.06	25.80	4.22	3	/
C6	20240613	Cloudy	13:59	8.34	103.7	8.27	0.13	26.50	5.07	4	/
C6	20240613	Cloudy	13:59	8.34	103.7	8.26	0.13	26.50	5.04	4	/
C6	20240615	Cloudy	9:30	8.34	104	8.11	0.11	26.80	5.27	4	/
C6	20240615	Cloudy	9:30	8.31	103.6	8.10	0.11	26.80	5.24	3	/
C6	20240618	Sunny	12:59	7.66	101	8.15	0.11	26.80	5.18	<2.5	/
C6	20240618	Sunny	12:59	7.74	102.1	8.15	0.11	26.80	5.24	<2.5	/
C6	20240620	Sunny	14:08	8.45	104.8	8.10	0.05	26.30	4.50	4	/
C6	20240620	Sunny	14:08	8.45	104.8	8.09	0.05	26.30	4.47	4	/
C6	20240622	Sunny	9:47	8.14	101.5	8.01	0.09	26.40	5.67	<2.5	/
C6	20240622	Sunny	9:47	8.11	101.1	8.01	0.09	26.40	5.64	<2.5	/
C6	20240625	Sunny	13:59	8.41	105	7.91	0.05	26.70	4.22	7	/
C6	20240625	Sunny	14:00	8.41	105	7.92	0.05	26.70	4.33	5	/
C6	20240627	Sunny	13:59	7.66	104.6	8.25	0.08	31.90	5.97	6	/
C6	20240627	Sunny	13:59	7.65	104.6	8.25	0.08	31.90	6.00	10	/
C6	20240629	Sunny	9:51	8.04	100.3	7.77	0.11	27.40	5.88	<2.5	/
C6	20240629	Sunny	9:51	8.01	99.9	7.77	0.11	27.40	5.79	<2.5	/

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C7A

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C7A	20240604	Cloudy	14:48	7.36	87.8	7.69	0.12	24.20	5.59	16	/
C7A	20240604	Cloudy	14:49	7.35	87.7	7.67	0.12	24.20	5.51	15	/
C7A	20240606	Cloudy	14:26	7.20	89.0	7.83	0.11	26.10	5.80	9	/
C7A	20240606	Cloudy	14:26	7.17	88.7	7.81	0.11	26.10	5.75	6	/
C7A	20240608	Cloudy	10:39	7.52	91.6	7.63	0.12	25.90	4.38	<2.5	/
C7A	20240608	Cloudy	10:39	7.77	94.6	7.65	0.12	25.90	4.25	<2.5	/
C7A	20240611	Cloudy	14:36	6.66	86.6	7.62	0.11	29.00	5.00	12	/
C7A	20240611	Cloudy	14:36	6.65	86.5	7.62	0.11	29.00	4.98	12	/
C7A	20240613	Cloudy	14:26	8.22	110.2	8.13	0.12	30.70	5.24	4	/
C7A	20240613	Cloudy	14:26	8.23	110.2	8.13	0.12	30.70	5.25	4	/
C7A	20240615	Cloudy	9:51	8.22	102.5	7.98	0.14	27.70	5.48	8.6	/
C7A	20240615	Cloudy	9:51	8.23	102.6	7.98	0.14	27.70	5.59	6	/
C7A	20240618	Sunny	13:28	8.10	106.8	8.11	0.16	29.50	5.33	<2.5	/
C7A	20240618	Sunny	13:28	8.13	107.2	8.11	0.16	29.50	5.35	<2.5	/
C7A	20240620	Sunny	14:33	7.43	100.4	7.98	0.10	31.20	7.40	4	/
C7A	20240620	Sunny	14:33	7.44	100.5	7.97	0.10	31.20	7.55	5	/
C7A	20240622	Sunny	10:09	7.36	91.8	7.97	0.10	28.30	5.18	<2.5	/
C7A	20240622	Sunny	10:09	7.41	92.4	7.97	0.10	28.30	5.09	<2.5	/
C7A	20240625	Sunny	14:30	9.22	124.6	8.17	0.09	31.20	5.65	3	/
C7A	20240625	Sunny	14:30	9.23	124.6	8.13	0.09	31.20	5.42	4	/
C7A	20240627	Sunny	14:13	6.39	86.2	8.03	0.10	31.10	6.89	5	/
C7A	20240627	Sunny	14:13	6.39	86.2	8.02	0.10	31.10	6.98	5	/
C7A	20240629	Sunny	10:14	6.68	83.3	7.58	0.09	28.60	5.63	<2.5	/
C7A	20240629	Sunny	10:14	6.73	83.9	7.58	0.09	28.60	5.58	<2.5	/

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -

Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che

Water Quality Monitoring Result



Water Quality Monitoring Location: C8

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C8	20240604	Cloudy	15:03	7.29	87.1	7.57	0.10	24.30	7.60	10	/
C8	20240604	Cloudy	15:04	7.28	87.0	7.56	0.10	24.30	7.19	8	/
C8	20240606	Cloudy	14:39	6.74	83.0	7.65	0.11	25.90	8.28	5	/
C8	20240606	Cloudy	14:39	6.70	82.6	7.63	0.11	25.90	8.48	4	/
C8	20240608	Cloudy	10:55	6.55	79.7	7.42	0.14	25.80	6.47	<2.5	/
C8	20240608	Cloudy	10:55	6.40	77.9	7.38	0.14	25.80	6.59	<2.5	/
C8	20240611	Cloudy	14:48	6.87	88.1	7.54	0.08	28.20	6.17	<2.5	/
C8	20240611	Cloudy	14:48	6.86	88.0	7.53	0.08	28.20	6.90	<2.5	/
C8	20240613	Cloudy	14:39	7.09	94.4	7.79	0.10	30.30	7.30	3	/
C8	20240613	Cloudy	14:39	7.09	94.3	7.78	0.10	30.30	7.37	<2.5	/
C8	20240615	Cloudy	10:04	7.09	88.4	7.63	0.08	28.10	6.18	4	/
C8	20240615	Cloudy	10:04	7.11	88.7	7.63	0.08	28.10	6.37	3	/
C8	20240618	Sunny	13:49	7.21	95.1	7.83	0.15	28.30	7.13	<2.5	/
C8	20240618	Sunny	13:49	7.24	95.5	7.85	0.15	28.30	7.07	<2.5	/
C8	20240620	Sunny	14:48	7.10	95.5	7.75	0.09	31.00	9.78	3	/
C8	20240620	Sunny	14:48	7.09	95.4	7.74	0.09	31.00	9.84	4	/
C8	20240622	Sunny	10:24	7.00	87.3	7.70	0.08	28.10	6.33	<2.5	/
C8	20240622	Sunny	10:24	6.99	87.2	7.70	0.08	28.10	6.49	<2.5	/
C8	20240625	Sunny	14:50	8.24	110.7	7.81	0.08	30.90	7.83	<2.5	/
C8	20240625	Sunny	14:50	8.24	110.8	7.79	0.08	30.90	7.76	3	/
C8	20240627	Sunny	14:26	6.64	88.7	7.94	0.10	30.50	8.42	4	/
C8	20240627	Sunny	14:26	6.63	88.5	7.92	0.10	30.50	8.32	4	/
C8	20240629	Sunny	10:29	6.35	79.2	7.63	0.06	28.50	6.48	<2.5	/
C8	20240629	Sunny	10:29	6.37	79.4	7.63	0.06	28.50	6.55	<2.5	/

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result



Water Quality Monitoring Location: C9

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C9	20240604	Cloudy	13:41	8.81	102.8	8.01	0.07	23.00	8.63	9	/
C9	20240604	Cloudy	13:41	8.81	102.6	7.99	0.07	23.00	8.45	11	/
C9	20240606	Cloudy	13:22	8.60	102.2	8.31	0.28	23.90	3.80	3	/
C9	20240606	Cloudy	13:22	8.60	102.1	8.29	0.28	23.90	4.00	3	/
C9	20240608	Cloudy	9:18	8.15	99.2	8.33	0.18	24.20	3.66	3	/
C9	20240608	Cloudy	9:18	8.00	97.4	8.38	0.18	24.20	3.79	3	/
C9	20240611	Cloudy	13:19	8.42	102.3	7.87	0.07	25.20	3.87	5	/
C9	20240611	Cloudy	13:19	8.42	102.3	7.86	0.07	25.20	3.73	6	/
C9	20240613	Cloudy	13:22	8.31	102.0	8.35	0.20	25.70	8.21	23	/
C9	20240613	Cloudy	13:22	8.30	101.9	8.33	0.20	25.70	7.85	22	/
C9	20240615	Cloudy	8:52	8.31	103.6	8.10	0.11	25.90	7.66	6	/
C9	20240615	Cloudy	8:52	8.30	103.5	8.10	0.11	25.90	7.51	4	/
C9	20240618	Sunny	12:18	8.26	108.9	8.10	0.11	26.10	8.14	3	/
C9	20240618	Sunny	12:18	8.25	108.8	8.08	0.11	26.10	7.99	<2.5	/
C9	20240620	Sunny	13:11	8.36	103.2	8.50	0.24	26.00	4.42	13	/
C9	20240620	Sunny	13:11	8.36	103.1	8.49	0.24	26.00	4.31	10	/
C9	20240622	Sunny	9:11	8.21	102.4	8.21	0.16	26.20	7.16	3	/
C9	20240622	Sunny	9:11	8.18	102.0	8.21	0.16	26.20	7.01	5	/
C9	20240625	Sunny	13:13	8.37	103.4	8.00	0.06	26.10	4.49	5	/
C9	20240625	Sunny	13:13	8.37	103.4	7.99	0.06	26.10	4.55	5	/
C9	20240627	Sunny	13:23	8.20	102.1	8.30	0.21	26.50	6.05	10	/
C9	20240627	Sunny	13:23	8.20	102.1	8.29	0.21	26.50	6.10	18	/
C9	20240629	Sunny	9:14	8.00	99.8	8.01	0.18	27.60	7.01	4	/
C9	20240629	Sunny	9:14	7.98	99.5	8.01	0.18	27.60	7.08	6	/

Contract No. DC/2022/02





Drainage Improvement Works at Yuen Long -
Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che
Water Quality Monitoring Result







Water Quality Monitoring Location: C10

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C10	20240604	Cloudy	13:53	7.13	83.6	7.69	0.06	23.20	8.76	4	/
C10	20240604	Cloudy	13:53	7.12	83.4	7.67	0.06	23.20	8.67	5	/
C10	20240606	Cloudy	13:36	6.14	73.9	8.07	0.08	24.70	7.84	3	/
C10	20240606	Cloudy	13:36	6.12	73.7	8.03	0.08	24.70	8.81	<2.5	/
C10	20240608	Cloudy	9:33	5.58	67.9	7.88	0.09	24.50	6.58	<2.5	/
C10	20240608	Cloudy	9:33	5.38	65.5	7.81	0.09	24.50	6.69	<2.5	/
C10	20240611	Cloudy	13:36	6.37	79.4	7.42	0.06	26.60	5.02	<2.5	/
C10	20240611	Cloudy	13:36	6.36	79.3	7.41	0.06	26.60	5.01	<2.5	/
C10	20240613	Cloudy	13:32	6.27	79.8	7.85	0.07	27.80	4.31	<2.5	/
C10	20240613	Cloudy	13:32	6.27	79.8	7.84	0.07	27.80	4.28	4	/
C10	20240615	Cloudy	9:06	6.27	78.2	7.88	0.07	26.80	5.49	3	/
C10	20240615	Cloudy	9:06	6.33	78.9	7.89	0.07	26.80	5.63	<2.5	/
C10	20240618	Sunny	12:30	5.11	67.4	7.93	0.08	27.20	5.68	<2.5	/
C10	20240618	Sunny	12:30	5.18	68.3	7.94	0.08	27.20	5.44	4	/
C10	20240620	Sunny	13:28	6.75	85.8	7.96	0.06	27.70	6.75	<2.5	/
C10	20240620	Sunny	13:28	6.75	85.7	7.96	0.06	27.70	6.77	3	/
C10	20240622	Sunny	9:24	5.36	66.8	7.55	0.05	27.10	6.33	3	/
C10	20240622	Sunny	9:24	5.47	68.2	7.56	0.05	27.10	6.45	4	/
C10	20240625	Sunny	13:25	4.52	58.0	7.65	0.11	28.20	7.56	<2.5	/
C10	20240625	Sunny	13:25	4.5	57.8	7.64	0.11	28.20	7.15	<2.5	/
C10	20240627	Sunny	13:33	6.24	81.2	8.1	0.09	29.00	9.83	<2.5	/
C10	20240627	Sunny	13:33	6.23	81.1	8.08	0.09	29.00	9.75	3	/
C10	20240629	Sunny	9:27	4.48	55.9	7.23	0.07	27.80	8.27	<2.5	/
C10	20240629	Sunny	9:27	4.55	56.7	7.23	0.07	27.80	8.44	<2.5	/





Monitoring Location: C10







Monitoring Location: C9







Monitoring Location: C8







Monitoring Location: C7A







Monitoring Location: C6



Monitoring Location: C3A



Monitoring Location: C2



Monitoring Location: C1A

