

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -

Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che

Water Quality Monitoring Result



Water Quality Monitoring Location: C1A

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C1A	20240801	Cloudy	15:30	6.81	91.8	7.40	0.06	29.80	4.88	<2.5	
C1A	20240801	Cloudy	15:30	6.77	91.2	7.40	0.06	29.80	4.96	<2.5	
C1A	20240803	Sunny	11:25	7.38	99.5	7.14	0.04	30.10	6.68	<2.5	
C1A	20240803	Sunny	11:25	7.25	97.7	7.15	0.04	30.10	6.73	<2.5	
C1A	20240806	Cloudy	15:36	7.13	93.7	7.12	0.08	31.40	4.55	<2.5	
C1A	20240806	Cloudy	15:36	7.21	94.8	7.13	0.08	31.40	4.63	2.7	
C1A	20240808	Cloudy	15:25	7.28	95.3	7.35	0.06	30.10	5.48	<2.5	
C1A	20240808	Cloudy	15:25	7.32	95.9	7.36	0.06	30.10	5.66	<2.5	
C1A	20240810	Cloudy	11:20	6.95	90.1	7.36	0.06	31.20	5.88	<2.5	
C1A	20240810	Cloudy	11:20	6.88	89.3	7.37	0.06	31.20	5.96	<2.5	
C1A	20240813	Cloudy	15:37	6.88	91.7	7.12	0.08	31.40	4.55	<2.5	
C1A	20240813	Cloudy	15:37	6.87	91.6	7.13	0.08	31.40	4.63	<2.5	
C1A	20240815	Cloudy	15:33	7.02	76.7	7.68	0.09	28.60	4.95	<2.5	
C1A	20240815	Cloudy	15:33	6.99	76.5	7.67	0.09	28.60	5.04	2.8	
C1A	20240817	Cloudy	11:06	7.39	81.1	7.43	0.11	28.10	4.96	7.6	
C1A	20240817	Cloudy	11:06	7.39	81.0	7.43	0.11	28.10	5.02	6.8	
C1A	20240820	Cloudy	15:48	7.18	96.8	7.68	0.07	29.10	5.44	<2.5	
C1A	20240820	Cloudy	15:48	7.20	97.0	7.68	0.07	29.10	5.48	<2.5	
C1A	20240822	Sunny	13:56	7.07	93.2	7.17	0.05	29.80	2.92	<2.5	
C1A	20240822	Sunny	13:56	7.11	93.7	7.18	0.05	29.80	3.08	<2.5	
C1A	20240824	Fine	8:35	8.59	104.8	7.31	0.07	25.30	2.98	<2.5	
C1A	20240824	Fine	8:35	8.62	104.9	7.36	0.08	25.40	3.02	<2.5	
C1A	20240827	Sunny	16:02	7.35	97.0	7.66	0.13	28.80	4.6	<2.5	
C1A	20240827	Sunny	16:02	7.34	96.8	7.65	0.13	28.80	4.69	<2.5	
C1A	20240829	Cloudy	13:26	7.08	88.0	7.52	0.10	28.50	5.33	<2.5	
C1A	20240829	Cloudy	13:26	7.08	87.9	7.51	0.10	28.50	5.58	<2.5	
C1A	20240831	Cloudy	10:33	7.35	93.2	7.58	0.12	28.10	4.99	<2.5	
C1A	20240831	Cloudy	10:33	7.34	93.0	7.58	0.12	28.10	4.94	<2.5	

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -

Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che

Water Quality Monitoring Result



Water Quality Monitoring Location: C2

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C2	20240801	Cloudy	15:15	6.50	87.6	7.21	0.08	30.20	5.31	6.9	
C2	20240801	Cloudy	15:15	6.66	89.7	7.23	0.08	30.20	5.39	8.6	
C2	20240803	Sunny	11:18	6.78	91.4	7.30	0.09	30.60	6.11	4.3	
C2	20240803	Sunny	11:18	6.83	92.1	7.31	0.09	30.60	6.09	4.7	
C2	20240806	Cloudy	15:22	6.90	90.7	7.33	0.09	30.80	6.35	6.8	
C2	20240806	Cloudy	15:22	6.85	90	7.34	0.09	30.80	6.42	4.4	
C2	20240808	Cloudy	15:18	7.11	93.1	7.20	0.10	29.80	6.21	4.2	
C2	20240808	Cloudy	15:18	7.13	93.4	7.20	0.10	29.80	6.29	<2.5	
C2	20240810	Cloudy	11:09	6.45	83.6	7.25	0.07	30.20	6.12	<2.5	
C2	20240810	Cloudy	10:10	6.39	82.9	7.26	0.07	30.20	6.04	<2.5	
C2	20240813	Cloudy	15:20	6.20	83.7	7.33	0.09	30.80	6.35	<2.5	
C2	20240813	Cloudy	15:20	6.15	83.0	7.34	0.09	30.80	6.42	2.9	
C2	20240815	Cloudy	15:26	6.50	70.9	8.13	0.11	27.20	4.56	6.3	
C2	20240815	Cloudy	15:26	6.47	70.7	8.12	0.11	27.20	4.69	3.8	
C2	20240817	Cloudy	10:55	6.48	71.3	7.90	0.12	28.00	4.4	13.0	
C2	20240817	Cloudy	10:55	6.47	71.1	7.90	0.12	28.00	4.41	13.0	
C2	20240820	Cloudy	15:40	6.88	92.7	7.88	0.06	28.60	6.33	<2.5	
C2	20240820	Cloudy	15:40	6.91	93.1	7.89	0.06	28.60	6.21	<2.5	
C2	20240822	Sunny	13:52	7.99	102.5	7.24	0.02	28.30	5.04	<2.5	
C2	20240822	Sunny	13:52	7.96	102.2	7.22	0.02	28.30	4.89	<2.5	
C2	20240824	Fine	8:46	7.56	103.5	7.21	0.05	26.80	4.92	2.7	
C2	20240824	Fine	8:46	7.65	103.8	7.34	0.05	26.90	4.86	2.9	
C2	20240827	Sunny	15:52	6.11	80.4	7.85	0.14	29.10	4.52	<2.5	
C2	20240827	Sunny	15:52	6.07	80.1	7.84	0.14	29.10	4.65	<2.5	
C2	20240829	Cloudy	13:16	6.35	78.8	7.75	0.11	28.80	6.91	<2.5	
C2	20240829	Cloudy	13:16	6.27	78.5	7.76	0.11	28.80	6.47	<2.5	
C2	20240831	Cloudy	10:25	6.32	79.9	7.84	0.14	27.80	5.44	<2.5	
C2	20240831	Cloudy	10:25	6.30	79.7	7.82	0.14	27.80	5.67	<2.5	

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -

Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che

Water Quality Monitoring Result



Water Quality Monitoring Location: C3A

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C3A	20240801	Cloudy	15:06	7.53	101.5	7.58	0.05	28.50	3.69	5.1	
C3A	20240801	Cloudy	15:07	7.36	99.2	7.54	0.05	28.50	3.71	6.0	
C3A	20240803	Sunny	10:59	6.99	94.2	7.48	0.03	28.90	3.43	5.0	
C3A	20240803	Sunny	11:00	7.03	94.8	7.44	0.03	28.90	3.21	<2.5	
C3A	20240806	Cloudy	15:11	7.59	99.8	7.38	0.05	29.30	3.21	4.1	
C3A	20240806	Cloudy	15:11	7.63	100.3	7.36	0.05	29.30	3.35	5.8	
C3A	20240808	Cloudy	15:01	7.69	100.7	7.29	0.06	29.10	3.05	<2.5	
C3A	20240808	Cloudy	15:01	7.73	101.2	7.29	0.06	29.10	2.91	<2.5	
C3A	20240810	Cloudy	10:58	8.01	102.3	7.45	0.04	29.50	2.88	<2.5	
C3A	20240810	Cloudy	10:58	7.89	100.8	7.45	0.04	29.50	2.95	2.8	
C3A	20240813	Cloudy	15:09	8.66	112.1	7.38	0.05	29.30	3.21	<2.5	
C3A	20240813	Cloudy	15:09	8.65	112.0	7.36	0.05	29.30	3.35	<2.5	
C3A	20240815	Cloudy	15:09	7.59	83.2	7.67	0.03	27.10	3.72	3.8	
C3A	20240815	Cloudy	15:09	7.58	83.4	7.63	0.03	27.10	3.62	3.1	
C3A	20240817	Cloudy	10:36	8.15	89.0	7.65	0.05	27.60	3.66	10.0	
C3A	20240817	Cloudy	10:36	8.19	89.4	7.62	0.05	27.60	3.47	13.0	
C3A	20240820	Cloudy	15:29	6.86	92.4	7.20	0.03	28.30	3.21	<2.5	
C3A	20240820	Cloudy	15:29	6.81	91.8	7.20	0.03	28.30	3.24	<2.5	
C3A	20240822	Sunny	13:44	8.04	102.2	7.37	0.02	27.70	5.42	<2.5	
C3A	20240822	Sunny	13:44	8.03	102.1	7.33	0.02	27.70	5.51	<2.5	
C3A	20240824	Fine	9:01	8.42	111.6	7.95	0.03	27.30	6.88	5.1	
C3A	20240824	Fine	9:01	8.37	111.9	7.89	0.03	27.40	6.87	7.6	
C3A	20240827	Sunny	15:36	8.46	110.7	7.86	0.01	27.50	3.83	<2.5	
C3A	20240827	Sunny	15:37	8.42	111.0	7.82	0.01	27.50	3.73	<2.5	
C3A	20240829	Cloudy	12:56	7.69	95.6	7.50	0.05	27.40	3.71	2.9	
C3A	20240829	Cloudy	12:56	7.72	95.9	7.46	0.05	27.40	3.41	3.3	
C3A	20240831	Cloudy	10:12	7.76	98.2	7.93	0.01	27.10	4.02	3.2	
C3A	20240831	Cloudy	10:12	7.83	98.5	7.88	0.01	27.10	3.7	3.9	

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -

Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che

Water Quality Monitoring Result



Water Quality Monitoring Location: C6

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C6	20240801	Cloudy	13:58	8.21	110.6	7.69	0.05	27.70	4.82	5.6	
C6	20240801	Cloudy	13:58	8.25	111.2	7.71	0.05	27.70	4.9	6.5	
C6	20240803	Sunny	9:30	7.68	103.5	7.76	0.08	28.10	6.03	2.9	
C6	20240803	Sunny	9:30	7.59	102.3	7.79	0.08	28.10	6.18	3.7	
C6	20240806	Cloudy	13:59	7.21	94.8	7.55	0.08	28.40	4.69	3.1	
C6	20240806	Cloudy	13:59	7.33	96.3	7.55	0.08	28.40	4.78	5.2	
C6	20240808	Cloudy	13:51	7.44	97.4	7.41	0.09	28.20	5.73	<2.5	
C6	20240808	Cloudy	13:51	7.46	97.7	7.41	0.09	28.20	5.88	<2.5	
C6	20240810	Cloudy	9:41	8.28	105.8	7.34	0.09	28.80	6.78	<2.5	
C6	20240810	Cloudy	9:41	8.34	106.5	7.34	0.09	28.80	6.89	<2.5	
C6	20240813	Cloudy	13:56	9.15	117.1	7.55	0.08	28.40	4.69	<2.5	
C6	20240813	Cloudy	13:56	9.15	117.1	7.55	0.08	28.40	4.78	<2.5	
C6	20240815	Cloudy	13:59	8.76	95.8	8.15	0.08	29.80	6.38	3.8	
C6	20240815	Cloudy	13:59	8.75	96.1	8.15	0.08	29.80	6.63	4.5	
C6	20240817	Cloudy	9:19	8.92	97.1	8.35	0.07	30.20	5.71	7.0	
C6	20240817	Cloudy	9:19	8.95	97.3	8.33	0.07	30.20	5.81	11.0	
C6	20240820	Cloudy	14:08	7.12	95.9	8.01	0.12	27.80	5.68	<2.5	
C6	20240820	Cloudy	14:08	7.09	95.5	8.01	0.12	27.80	5.73	<2.5	
C6	20240822	Sunny	12:47	6.38	82.3	7.29	0.09	28.60	4.16	3.5	
C6	20240822	Sunny	12:47	6.37	82.2	7.28	0.09	28.60	4.28	3.9	
C6	20240824	Fine	9:14	8.45	116.5	7.81	0.06	27.10	4.86	13.0	
C6	20240824	Fine	9:14	8.49	116.8	7.92	0.06	27.30	4.82	8.0	
C6	20240827	Sunny	14:21	8.17	107.5	7.99	0.06	27.70	6.16	<2.5	
C6	20240827	Sunny	14:21	8.22	107.9	7.99	0.06	27.70	6.41	<2.5	
C6	20240829	Cloudy	11:47	8.13	101.1	8.29	0.06	29.60	6.42	5.6	
C6	20240829	Cloudy	11:47	8.15	101.5	8.27	0.06	29.60	6.74	8.3	
C6	20240831	Cloudy	9:18	8.41	106.5	7.97	0.07	29.50	7.28	<2.5	
C6	20240831	Cloudy	9:18	8.49	106.9	7.99	0.07	29.50	7.66	<2.5	

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -

Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che

Water Quality Monitoring Result



Water Quality Monitoring Location: C7A

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C7A	20240801	Cloudy	14:25	5.44	73.3	7.31	0.12	29.10	4.11	5.2	
C7A	20240801	Cloudy	14:25	5.56	74.9	7.33	0.12	29.10	3.99	5.6	
C7A	20240803	Sunny	10:00	6.01	81.0	7.15	0.15	29.30	4.59	6.0	
C7A	20240803	Sunny	10:00	5.86	79.0	7.18	0.15	29.30	4.67	6.9	
C7A	20240806	Cloudy	14:24	6.21	81.6	7.20	0.14	29.80	3.88	6.4	
C7A	20240806	Cloudy	14:24	6.28	82.5	7.20	0.14	29.80	3.95	7.4	
C7A	20240808	Cloudy	14:18	6.99	89.1	7.26	0.13	29.50	4.28	2.5	
C7A	20240808	Cloudy	14:18	7.03	89.6	7.26	0.13	29.50	4.39	2.6	
C7A	20240810	Cloudy	10:04	5.58	71.3	7.21	0.11	29.40	5.44	<2.5	
C7A	20240810	Cloudy	10:04	5.67	72.4	7.20	0.11	29.40	5.38	3.3	
C7A	20240813	Cloudy	14:25	4.93	64.8	7.20	0.14	29.80	3.88	<2.5	
C7A	20240813	Cloudy	14:25	4.90	64.4	7.20	0.14	29.80	3.95	4.3	
C7A	20240815	Cloudy	14:26	7.20	78.6	7.60	0.14	28.60	7.32	5.0	
C7A	20240815	Cloudy	14:26	7.14	78.5	7.57	0.14	28.60	6.99	6.2	
C7A	20240817	Cloudy	9:42	7.47	82.2	7.55	0.12	28.50	8.32	11.0	
C7A	20240817	Cloudy	9:42	7.52	82.1	7.52	0.12	28.50	7.31	12.0	
C7A	20240820	Cloudy	14:43	6.33	85.4	7.98	0.14	29.70	5.69	<2.5	
C7A	20240820	Cloudy	14:43	6.38	86.1	7.98	0.14	29.70	5.73	3.6	
C7A	20240822	Sunny	13:03	6.68	89.0	7.60	0.13	30.40	4.3	9.5	
C7A	20240822	Sunny	13:04	6.67	88.9	7.58	0.13	30.40	4.28	9.2	
C7A	20240824	Fine	9:23	6.58	89.6	7.65	0.08	27.80	5.66	11.0	
C7A	20240824	Fine	9:23	6.61	89.3	7.67	0.08	27.80	5.68	15.0	
C7A	20240827	Sunny	14:45	7.72	101.4	7.81	0.11	28.40	7.63	2.8	
C7A	20240827	Sunny	14:45	7.70	101.3	7.78	0.11	28.40	7.3	<2.5	
C7A	20240829	Cloudy	12:12	7.76	96.7	7.64	0.11	28.70	7.74	10.0	
C7A	20240829	Cloudy	12:12	7.78	96.6	7.48	0.11	28.70	6.88	10.0	
C7A	20240831	Cloudy	9:30	7.33	92.4	7.91	0.12	29.10	7.21	<2.5	
C7A	20240831	Cloudy	9:30	7.30	92.3	7.90	0.12	29.10	6.78	<2.5	

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -

Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che

Water Quality Monitoring Result



Water Quality Monitoring Location: C8

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C8	20240801	Cloudy	14:38	7.77	104.7	7.45	0.09	28.80	5.87	<2.5	
C8	20240801	Cloudy	14:38	7.83	105.5	7.44	0.09	28.80	5.73	<2.5	
C8	20240803	Sunny	10:16	7.63	102.9	7.36	0.08	29.00	5.11	<2.5	
C8	20240803	Sunny	10:16	7.70	103.8	7.38	0.08	29.00	5.05	<2.5	
C8	20240806	Cloudy	14:39	7.09	93.2	7.48	0.07	30.00	5.48	<2.5	
C8	20240806	Cloudy	14:39	7.22	94.9	7.48	0.07	30.00	5.61	2.7	
C8	20240808	Cloudy	14:33	7.58	96.6	7.35	0.06	29.90	5.66	<2.5	
C8	20240808	Cloudy	14:33	7.65	97.5	7.36	0.06	29.90	5.78	<2.5	
C8	20240810	Cloudy	10:25	7.48	95.5	7.40	0.06	29.90	5.66	<2.5	
C8	20240810	Cloudy	10:25	7.59	97.0	7.40	0.06	29.90	5.73	<2.5	
C8	20240813	Cloudy	14:38	8.06	106.0	7.48	0.07	30.00	5.48	<2.5	
C8	20240813	Cloudy	14:38	8.05	105.8	7.48	0.07	30.00	5.61	<2.5	
C8	20240815	Cloudy	14:44	6.77	74.3	7.62	0.13	28.10	7.76	3.0	
C8	20240815	Cloudy	14:45	6.78	74.1	7.60	0.13	28.10	7.85	<2.5	
C8	20240817	Cloudy	9:59	7.51	82.3	7.66	0.13	28.00	7.68	2.3	
C8	20240817	Cloudy	9:59	7.49	82.1	7.62	0.13	28.00	7.24	3.3	
C8	20240820	Cloudy	14:59	7.28	98.1	7.77	0.09	28.80	6.29	<2.5	
C8	20240820	Cloudy	15:00	7.31	98.5	7.77	0.09	28.80	6.35	<2.5	
C8	20240822	Sunny	13:17	6.53	86.0	7.48	0.09	29.70	5.41	3.5	
C8	20240822	Sunny	13:18	6.28	82.7	7.41	0.09	29.70	5.81	2.9	
C8	20240824	Fine	9:50	7.65	103.6	7.58	0.09	28.10	6.52	5.4	
C8	20240824	Fine	9:50	7.69	104.7	7.62	0.09	28.00	6.56	6.8	
C8	20240827	Sunny	15:03	7.03	92.4	7.85	0.13	28.90	7.5	<2.5	
C8	20240827	Sunny	15:03	7.01	92.1	7.83	0.13	28.90	7.59	<2.5	
C8	20240829	Cloudy	12:28	7.62	95.0	7.57	0.13	28.50	7.95	3.3	
C8	20240829	Cloudy	12:28	7.58	94.7	7.53	0.13	28.50	7.54	4.0	
C8	20240831	Cloudy	9:40	6.88	86.7	7.44	0.09	27.70	7.87	<2.5	
C8	20240831	Cloudy	9:40	6.87	86.5	7.43	0.09	27.70	7.94	<2.5	

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -

Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che

Water Quality Monitoring Result



Water Quality Monitoring Location: C9

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C9	20240801	Cloudy	13:15	8.68	116.9	7.68	0.04	26.90	3.77	5.1	
C9	20240801	Cloudy	13:15	8.79	118.4	7.63	0.04	26.90	3.85	5.9	
C9	20240803	Sunny	8:46	8.11	109.3	7.61	0.06	27.60	4.11	<2.5	
C9	20240803	Sunny	8:46	8.06	108.7	7.59	0.06	27.70	4.15	<2.5	
C9	20240806	Cloudy	13:12	8.35	109.7	7.66	0.06	27.20	5.11	3.4	
C9	20240806	Cloudy	13:12	8.46	111.2	7.66	0.06	27.20	5.28	3.0	
C9	20240808	Cloudy	13:10	8.01	96.8	7.68	0.08	27.80	6.13	<2.5	
C9	20240808	Cloudy	13:10	7.99	96.6	7.68	0.08	27.80	6.22	<2.5	
C9	20240810	Cloudy	8:49	8.46	108.1	7.53	0.08	27.50	4.21	<2.5	
C9	20240810	Cloudy	8:50	8.57	109.5	7.53	0.08	27.50	4.33	<2.5	
C9	20240813	Cloudy	13:11	9.19	114.8	7.66	0.06	27.20	5.11	<2.5	
C9	20240813	Cloudy	13:11	9.18	114.7	7.66	0.06	27.20	5.28	<2.5	
C9	20240815	Cloudy	13:13	8.35	91.8	7.78	0.07	26.80	6.17	4.3	
C9	20240815	Cloudy	13:13	8.37	91.7	7.75	0.07	26.80	6.61	5.7	
C9	20240817	Cloudy	8:38	8.71	95.1	7.98	0.11	27.20	5.96	7.6	
C9	20240817	Cloudy	8:38	8.66	95.0	7.94	0.11	27.20	6.44	8.1	
C9	20240820	Cloudy	13:19	8.01	106.0	7.98	0.11	27.90	7.11	2.5	
C9	20240820	Cloudy	13:19	7.98	105.6	7.98	0.11	27.90	7.08	2.9	
C9	20240822	Sunny	11:58	8.58	105.6	7.95	0.05	25.90	8.73	8.3	
C9	20240822	Sunny	11:58	8.59	105.6	7.94	0.05	25.90	8.41	8.9	
C9	20240824	Fine	10:16	8.69	111.6	7.59	0.06	26.80	8.22	10.0	
C9	20240824	Fine	10:16	8.74	111.9	7.46	0.06	26.90	8.24	8.1	
C9	20240827	Sunny	13:40	8.13	106.7	7.68	0.09	26.80	6.45	<2.5	
C9	20240827	Sunny	13:40	8.14	106.5	7.65	0.09	26.80	6.89	<2.5	
C9	20240829	Cloudy	11:07	9.10	113.6	7.94	0.11	26.20	6.14	3.6	
C9	20240829	Cloudy	11:07	9.10	113.4	7.91	0.11	26.20	6.26	4.9	
C9	20240831	Cloudy	8:41	8.49	106.9	8.05	0.10	27.10	5.84	<2.5	
C9	20240831	Cloudy	8:41	8.46	106.8	8.04	0.10	27.10	6.44	<2.5	

Contract No. DC/2022/02

Drainage Improvement Works at Yuen Long -

Sung Shan New Village, Tai Wo, Lin Fa Tei and Ha Che





Water Quality Monitoring Result







Water Quality Monitoring Location: C10

Location	Date	Weather	Time	DO (mg/L)	Do Saturation (%)	pH	Sal (ppt)	Temp (°C)	Turbidity (NTU)	SS (mg/L)	Remark
C10	20240801	Cloudy	13:26	6.23	83.9	7.55	0.03	28.10	9.21	<2.5	
C10	20240801	Cloudy	13:26	6.17	83.1	7.58	0.03	28.10	9.13	<2.5	
C10	20240803	Sunny	8:59	6.83	92.1	7.66	0.07	28.40	6.21	<2.5	
C10	20240803	Sunny	8:59	6.97	94.0	7.68	0.07	28.40	6.35	<2.5	
C10	20240806	Cloudy	13:24	7.54	99.1	7.44	0.08	28.30	8.73	<2.5	
C10	20240806	Cloudy	13:24	7.33	96.3	7.44	0.08	28.30	8.54	<2.5	
C10	20240808	Cloudy	13:20	7.25	87.6	7.33	0.09	28.20	8.25	<2.5	
C10	20240808	Cloudy	13:21	7.18	86.8	7.34	0.09	28.20	8.16	<2.5	
C10	20240810	Cloudy	9:03	7.14	91.2	7.48	0.06	28.60	7.98	<2.5	
C10	20240810	Cloudy	9:03	7.27	92.9	7.48	0.06	28.60	8.21	<2.5	
C10	20240813	Cloudy	13:22	6.84	87.5	7.44	0.08	28.30	8.73	<2.5	
C10	20240813	Cloudy	13:22	6.77	86.7	7.44	0.08	28.30	8.54	<2.5	
C10	20240815	Cloudy	13:25	5.53	60.3	7.66	0.10	26.80	8.76	<2.5	
C10	20240815	Cloudy	13:25	5.41	59.4	7.66	0.10	26.80	8.21	<2.5	
C10	20240817	Cloudy	8:50	5.98	65.2	7.49	0.10	26.90	8.95	3.3	
C10	20240817	Cloudy	8:50	5.88	64.3	7.49	0.10	26.90	8.47	3.3	
C10	20240820	Cloudy	13:33	6.77	89.6	7.88	0.07	28.10	6.33	<2.5	
C10	20240820	Cloudy	13:33	6.73	89.1	7.89	0.07	28.10	6.39	<2.5	
C10	20240822	Sunny	12:16	6.75	85.9	7.61	0.06	27.80	7.34	<2.5	
C10	20240822	Sunny	12:16	6.73	85.6	7.55	0.06	27.80	7.45	<2.5	
C10	20240824	Fine	10:41	7.20	94.2	7.54	0.07	27.80	10.63	4.9	
C10	20240824	Fine	10:41	7.16	94.3	7.51	0.07	27.80	10.65	3.6	
C10	20240827	Sunny	13:55	5.35	70.4	7.46	0.10	27.10	9.04	<2.5	
C10	20240827	Sunny	13:55	5.27	69.4	7.46	0.10	27.10	8.49	<2.5	
C10	20240829	Cloudy	11:17	4.98	61.7	7.36	0.12	27.30	8.94	<2.5	
C10	20240829	Cloudy	11:17	4.84	60.7	7.38	0.12	27.30	8.14	<2.5	
C10	20240831	Cloudy	8:51	5.31	67.0	7.67	0.10	26.60	9.98	<2.5	
C10	20240831	Cloudy	8:51	5.25	66.0	7.69	0.10	26.60	10.11	<2.5	





Monitoring Location: C10







Monitoring Location: C9







Monitoring Location: C8







Monitoring Location: C7A







Monitoring Location: C6



Monitoring Location: C3A



Monitoring Location: C2



Monitoring Location: C1A

